

Overall report severity based on comments.

Account Information	Component Information	Sample Information
Account Number: OILANA-7502-2630 Company Name: STEVE NEW Contact: XXXXXXXXXX Address: 624 NW 31 STREET MIAMI, FL 33128 US Phone Number: 305-297-7664	Component ID: BLUE BRUTE E Secondary ID: 2013 RAM 2500 Component Type: DIESEL ENGINE Manufacturer: CUMMINS Model: ISB6.7 Application: AUTOMOTIVE Sump Capacity: 3 gal	Tracking Number: 18195Z01147 Lab Number: I-147418 Lab Location: Indianapolis Data Analyst: FLG Sampled: 19-Oct-2018 Received: 25-Oct-2018 Completed: 26-Oct-2018
Filter Information	Miscellaneous Information	Product Information
Filter Type: FULLFLOW & BYPASS Micron Rating: 0		Product Manufacturer: KENDALL Product Name: SUPER-D XA Viscosity Grade: SAE 15W40
Comments	Data indicates no abnormal findings. Resample at normal interval. Lubricant and filter change acknowledged.	

	Wear Metals (ppm)										Contaminant Metals (ppm)		Multi-Source Metals (ppm)						Additive Metals (ppm)					
Sample #	Iron	Chromium	Nickel	Aluminum	Copper	Lead	Tin	Cadmium	Silver	Vanadium	Silicon	Sodium	Potassium	Titanium	Molybdenum	Antimony	Manganese	Lithium	Boron	Magnesium	Calcium	Barium	Phosphorus	Zinc
1	11	0	0	1	1	0	0	0	0	0	6	6	1	89	4	0	0	0	96	405	1665	0	927	1082
2	4	0	1	0	0	0	0	0	0	0	7	2	1	93	0	1	0	0	122	411	1657	0	1006	1109

Sample Information								Contaminants			Fluid Properties					
Sample #	Date Sampled	Date Received	Lube Time	Unit Time	Lube Change	Lube Added	Filter Change	Fuel Dilution	Soot	Water	Viscosity 40°C	Viscosity 100 °C	Acid Number	Base No. D4739	Oxidation	Nitration
			mi	mi		gal		% Vol	% Vol	% Vol	cSt	cSt	mg KOH/g	mg KOH/g	abs/cm	abs/0.1 mm
1	01-Sep-2018	10-Sep-2018	3616	47616	No	0	No	8.4 - GC	0.4 - E2412	<.1 - FTIR		12.2		4.94	15	9
2	19-Oct-2018	25-Oct-2018	980	48856	Yes	0	Yes	<1 - Estimate	0.2 - E2412	<.1 - FTIR		13.4		5.90	12	7

	Particle Count (particles/mL)										Additional Testing					
Sample #	ISO Code															
	Based On 4/6/14	> 4 µm	> 6 µm	> 10 µm	> 14 µm	> 21 µm	> 38 µm	> 70 µm	> 100 µm	Test Method						
1	//															
2	//															

Comments are advisory only and are based on the assumption that the sample and data submitted are valid. Missing fluid or component information limits the evaluation. No warranty is expressed or implied. Measurement uncertainty available upon request.

Historical Comments	
1	Check for source of FUEL LEAK. Fuel is at a SEVERE LEVEL. Fuel dilution may be caused by component faults related to injectors, ignition/timing, or excessive blow-by. Additional causes include heavy throttle application, engine lugging, frequent short trips and excessive idling. LUBRICANT and FILTER CHANGE is suggested if not done at sampling time. FUEL DILUTION has caused viscosity to decrease slightly below grade; FUEL DILUTION reduces the viscosity of the lubricant which decreases FILM STRENGTH and LUBRICITY and may lead to increased wear. Resample at half interval.

