

ALL TECHNICAL SERVICE BULLETINS

☰ Type term and hit enter to filter list below

TSB NUMBER	TSB DATE	TSB TITLE
31-001-21	2021/04/10	Steering System Inspection After a Collision
23-043-20	2020/12/10	Headlamp Condensation and Fogging
31-002-20	2020/10/27	Aluminum Body Panel Corrosion Repair
08-092-20	2020/10/09	Improper Up Shift With Paddle Shift
23-015-20 REV. A	2020/06/19	Disinfectant Solution Recommended for COVID-19
18-039-20	2020/04/21	Possible Driveability Issues due to the Winter-Blend Fuel into the Warmer Season
31-001-20	2020/02/11	Blending Clearcoat During The Refinish Process
31-006-19	2019/11/20	Repair Parts Used For Structural Repairs
31-004-19	2019/11/20	Authentic Mopar® Glass Replacement
31-005-19	2019/11/20	Use of Aftermarket Parts
31-003-19	2019/11/20	Use of Salvage/Recycled Parts
24-012-19	2019/10/11	Flash: HVAC System Enhancement
31-002-19	2019/09/25	Scan Tool Support Before and After Collision Repair
31-002-18	2018/11/10	Safety Certification and Tire Pressure Label Replacement Guidelines
26-001-18	2018/09/21	Fluid Flushing Requirements
23-037-18	2018/09/19	Decklid Will Not Open
09-007-18 REV. A	2018/08/08	Engine Oil Consumption Guideline
RC-U60-18	2018/07/20	Safety Recall U60 / NHTSA 18V-332 Reprogram Powertrain Control Module
RC-CU60-18	2018/07/20	Safety Recall U60 Reprogram Powertrain Control Module

TSB NUMBER	TSB DATE	TSB TITLE
24-008-18	2018/07/13	A/C Systems Contain Fluorescent Leak Check Dye in Factory Fill
08-071-18	2018/05/16	UAS, UCQ, UDQ, UJQ and UAQ Radio Enhancements
08-003-18 REV. B	2018/05/10	RJ3 and RJ4 Radio Enhancements
RC-U22-18	2018/05/03	Customer Satisfaction Notification U22 Informative Spare Tire Label
RC-CU22-18	2018/05/01	Customer Satisfaction Notification U22 Informative Spare Tire Label
21-008-18	2018/02/07	Flash: Transmission Diagnostic and Shift Enhancements
05-006-17	2017/12/20	Noise While Braking
23-049-17	2017/11/03	Creaking Noise Coming From Driver's Front Power Seat
08-098-17	2017/09/29	Display Screen Module (DSM) Software Enhancements
08-070-17	2017/08/09	UAQ Radio Enhancements
23-020-17_REV._A	2017/05/06	Day Light Opening (DLO) Molding Loose
19-001-17	2017/04/26	Electric Power Steering (EPS) Module Connector Security
23-020-17	2017/04/25	Day Light Opening (DLO) Molding Loose
02-001-17_REV._A	2017/04/14	Tension Strut Bushing Replacement
04-001-17	2017/03/18	Failure Code Change
23-012-17_REV._A	2017/03/14	Wheel Liner Push Pin Fastener Replacement
21-003-17	2017/01/10	Flash - Transmission Diagnostic And Shift Enhancements
03-008-16	2016/12/23	Rear Axle Noise
08-090-16	2016/11/22	Shortened Battery Life
02-005-16	2016/10/21	Tension Strut Bushing Replacement
23-037-15	2015/10/14	Windshield Wiper Blade/Element Maintenance