

ALL TECHNICAL SERVICE BULLETINS

 Type term and hit enter to filter list below

TSB NUMBER	TSB DATE	TSB TITLE
RC-CV06-19	2021/05/24	Safety Recall V06 Drag Link
RC-V06-19	2021/05/24	Safety Recall V06 / NHTSA 19V-021 Drag Link
31-001-21	2021/04/10	Steering System Inspection After a Collision
08-094-20	2020/10/10	Flash: Drivetrain Control Module (DTCM) Update
RC-W49-20	2020/07/17	Equipment Safety Recall W49 NHTSA 20E-043 Drag Link
RC-CW49-20	2020/07/17	Campaign W49 Drag Link
23-015-20 REV. A	2020/06/19	Disinfectant Solution Recommended for COVID-19
23-016-20	2020/06/03	5th Wheel/Gooseneck Trailer Hitch Does Not Fit
03-001-20	2020/05/09	Rear Axle Vibration, Shudder Or Chatter
18-039-20	2020/04/21	Possible Driveability Issues due to the Winter-Blend Fuel into the Warmer Season
18-036-20	2020/04/09	Flash: Powertrain Control Module (PCM) Updates
31-001-20	2020/02/11	Blending Clearcoat During The Refinish Process
31-006-19	2019/11/20	Repair Parts Used For Structural Repairs
31-004-19	2019/11/20	Authentic Mopar® Glass Replacement
31-005-19	2019/11/20	Use of Aftermarket Parts
31-003-19	2019/11/20	Use of Salvage/Recycled Parts
08-016-19 REV. F	2019/10/19	UAS, UAQ, UCS and UCQ Radio Enhancements
31-002-19	2019/09/25	Scan Tool Support Before and After Collision Repair
RC-CV44-19	2019/09/05	Safety Recall V44 (Transport Canada No. 2019-441) Tailgate Latch
RC-V44-19	2019/09/05	Safety Recall V44 / NHTSA 19V-347 Tailgate Latch

TSB NUMBER	TSB DATE	TSB TITLE
19-001-19	2019/06/20	Toe Adjustment With Welded Drag Link
RC-U40-19	2019/03/21	Equipment Safety Recall U40 NHTSA 18E-028 Mopar Gooseneck Ball Kit
RC-CU40-18	2019/03/20	Campaign U40 Mopar Gooseneck Ball Kit
RC-CU11-18	2019/01/16	Safety Recall U11 Brake Transmission Shift Interlock
RC-U11-18	2019/01/14	Safety Recall U11 / NHTSA 18V-100 Brake Transmission Shift Interlock
31-002-18	2018/11/10	Safety Certification and Tire Pressure Label Replacement Guidelines
RC-U53-18	2018/11/06	Customer Satisfaction Notification U53 Occupant Restraint Control Module
RC-CU53-18	2018/11/06	Customer Satisfaction Notification U53 Occupant Restraint Control Module
08-131-18	2018/10/05	UAQ Radio Replacement
26-001-18	2018/09/21	Fluid Flushing Requirements
RC-CT82-18	2018/09/19	Safety Recall T82 Fire Extinguisher
09-007-18 REV. A	2018/08/08	Engine Oil Consumption Guideline
RC-U56-18	2018/07/26	Safety Recall U56 / NHTSA 18V-398 Rear View Mirror
RC-CU56-18	2018/07/24	Safety Recall U56 Rear View Mirror
08-008-18 REV. A	2018/07/14	UAS, UAQ, UCS and UCQ Radio Over The Air Software Version Updates
24-008-18	2018/07/13	A/C Systems Contain Fluorescent Leak Check Dye in Factory Fill
RC-CU61-18	2018/06/27	Safety Recall U61 Reprogram Powertrain Control Module
RC-U61-18	2018/06/26	Safety Recall U61 / NHTSA 18V-332 Reprogram Powertrain Control Module
23-027-18	2018/06/19	Outside Power Fold Mirror Binding or Clicking at Pivot
23-024-18	2018/06/13	Cleaning Marks or Stains on Platinum Colored Exterior Rearview Mirrors

TSB NUMBER	TSB DATE	TSB TITLE
RC-T82-18	2018/05/03	Safety Recall T82 / NHTSA 17V-824 Fire Extinguisher
RC-U15-18	2018/04/26	Emissions Recall U15 VECI Label
23-014-18 REV. A	2018/04/20	Cracked Clearance Lamp Lenses
RC-T83-18	2018/02/01	Safety Recall T83 / NHTSA 17E-076 Fire Extinguisher
08-115-17	2017/12/19	Flash: Park Assist Module (PAM) Diagnostic and System Improvements
23-037-15	2015/10/14	Windshield Wiper Blade/Element Maintenance