

## ALL TECHNICAL SERVICE BULLETINS

 Type term and hit enter to filter list below

| TSB NUMBER | TSB DATE   | TSB TITLE                                                      |
|------------|------------|----------------------------------------------------------------|
| 07-085     | 2015/11/12 | A/T - ATF Leak Detection Information                           |
| SN-13-12-3 | 2013/12/01 | A/C - Best Way to Control Musty Evaporator Odors               |
| 90-028     | 2013/09/24 | Body - Window Glass Markings                                   |
| SN-13-09-2 | 2013/09/01 | Restraints - Tips For Removing Stripped T30 Torx(R) Bolts      |
| SN-13-07-2 | 2013/07/01 | Vehicle - Silence Squeaks With T68 Lubricating Oil             |
| SN-13-07-3 | 2013/07/01 | Interior - Gaps, Squeaks, Rattles? Try Urethane Foam           |
| SN-13-04-2 | 2013/04/01 | A/C - Follow Proper Diagnostic Procedures                      |
| 09-060     | 2013/03/27 | Electrical - GR8 Battery Diagnostic Station Update Information |
| SN-13-03-2 | 2013/03/01 | Instruments - Odometer Mileage Transfer Information            |
| SN-12-11-3 | 2012/11/01 | Tires - Filling the Tires With Nitrogen, Honda(R) Says NO      |
| SN10110H   | 2012/11/01 | A/T - New ATF DW-1 Available                                   |
| SN-12-08-4 | 2012/08/01 | Restraints - Dealing With Common Seat Belt Complaints          |
| SN-12-07-2 | 2012/07/01 | A/C - Left Dash Vent Air is Warmer Than Right One              |
| SN-12-04-4 | 2012/04/01 | Fuel System - Gasoline Alcohol Percentage Tester               |
| 98-011     | 2011/06/25 | Keyless Entry - Keyless Remote Transmitter Information         |
| 98-074     | 2010/03/04 | Emissions - Hesitation/Stumble On Accel/Multiple DTC's         |
| 06-068     | 2009/05/02 | Steering/Suspension - Vehicle Pulls Left/Right                 |
| 89-022     | 2008/05/16 | A/T - Cooler Flushing Equipment Information                    |
| 07-008     | 2007/02/02 | Body - Unibody Repair Guidelines                               |
| 99-062     | 2007/01/15 | Paint Damage From Environmental Fallout                        |
| 06-082     | 2006/12/15 | Tires - Tubless Tire Repair Information                        |

| TSB NUMBER  | TSB DATE   | TSB TITLE                                             |
|-------------|------------|-------------------------------------------------------|
| SN051200-02 | 2005/12/01 | Starting System - Unable To Key In Ignition Switch    |
| SN051100-07 | 2005/11/01 | Interior - Fabric Upholstery Wrinkle Information      |
| SN051100-09 | 2005/11/01 | Engine - Connecting Rod Damage Information            |
| SN051100-11 | 2005/11/01 | Body - Chrome/Stainless Trim Staining Information     |
| SN050800-07 | 2005/08/01 | A/T - ATF Cooler Cleaner Information                  |
| SN050600-08 | 2005/06/01 | A/C - Heater Blows Cold Air/A/C Blows Hot Air         |
| SN050508    | 2005/05/01 | Exhaust System - Catalytic Converter Noise            |
| SN050506    | 2005/05/01 | Wind Noise - Simple Way To Replicate                  |
| SN050109    | 2005/01/01 | Engine - Oil Recommendation GF-4 Standard             |
| SN031107    | 2003/11/01 | Blower (Heater) Motor Gets Hot and Blows A Fuse       |
| 98-018      | 2003/07/22 | Drivetrain - Revised CV Joint Boot Band/Installation  |
| SN030706    | 2003/07/01 | Ceiling Light Doesn't Work                            |
| 00-099      | 2000/12/19 | Wiring Terminal - Repair Instructions                 |
| 00-089      | 2000/10/31 | Supplemental Restraint System - Inspection            |
| 00-022      | 2000/03/07 | Torque Converter Oil Seal - Installation Tool         |
| 97-015      | 1999/12/07 | Service Publications - Availability and Ordering      |
| 99-037      | 1999/05/25 | Front Balancer Shaft Oil Seal Installation Tool       |
| 91-029      | 1999/01/26 | Drivetrain - Clicking Noise On Low Speed Turns        |
| 98-001      | 1998/02/23 | Engine/Transmission - Hydraulic Lift Truck usage      |
| 86-020      | 1997/05/27 | Brakes - Disc Refinishing Procedure                   |
| 97-018      | 1997/03/31 | Suspension - Rear Wheel Bearing Noise                 |
| 97-028      | 1997/03/31 | Body - Minor Paint Finish Repair                      |
| 97-020      | 1997/03/10 | Tools - New Fuel Pressure Gauge and Replacement Parts |
| 96-046      | 1996/10/21 | Keyless Entry - Transmitter Programming Information   |
| 96042       | 1996/09/03 | Tools - Power Steering Pressure Gauge                 |

| TSB NUMBER     | TSB DATE   | TSB TITLE                                                |
|----------------|------------|----------------------------------------------------------|
| 89004          | 1996/05/06 | Required Special Tools and Equipment                     |
| 96014          | 1996/02/20 | Tools - Belt Tension Gauge Calibration and Repair        |
| 96005          | 1996/01/22 | Engine - Idle Vibration or 'Click'                       |
| 94007          | 1996/01/22 | Seat Belts - Availability of New Parts                   |
| 95028          | 1995/10/10 | Recall - Front Seat Belt Buckle                          |
| 95024          | 1995/07/17 | Airbag - Cable Reel Holding Fixture                      |
| 95020          | 1995/06/26 | A/C - Converting R-12 Systems to R-134a                  |
| NHTSA95V103001 | 1995/05/16 | Recall 95V103001: Seat Belt Buckle Failure               |
| 93011          | 1995/01/16 | Alignment - Premature/Irregular Front and Rear Tire Wear |
| ATRATB294      | 1995/01/01 | A/T - Drive Axle and Wheel Lug Nut Torque Specifications |
| 94043          | 1994/12/05 | Charging System - Alternator Bearing Noise               |
| 94025          | 1994/08/22 | Steering - Wheel Oscillates or Has a Shimmy              |
| 88012          | 1994/08/08 | Tools - Exacta Code Key Cutter                           |
| 93005          | 1994/06/24 | Body - Doors Hard To Open Or Close                       |
| 92004          | 1994/06/17 | Steering - Power Steering Rack Squeaks                   |
| 91010          | 1994/06/10 | Window - Rattles While Partially Opened                  |
| 94011          | 1994/05/13 | Radio - Poor Reception Or Interference                   |
| 91017          | 1994/02/04 | Sunroof - Rattle When Partially Open                     |
| 91008          | 1994/01/07 | Lighting - Buzzing During Turn Signal Lever Operation    |
| ATRATB208      | 1994/01/01 | A/T - No Upshift No Line Pressure After Rebuild          |
| 93035          | 1993/12/10 | Campaign - Distributor Defect                            |
| 93046          | 1993/10/29 | Mirrors - Rearview Mirror Tension Adjustment             |
| ATRATB191      | 1993/10/01 | A/T - Failsafe Modes                                     |
| ATRATB187      | 1993/10/01 | A/T - Trouble Codes                                      |
| 93019          | 1993/06/25 | Recall - Rear Seat Belt Retractor Sensor                 |

| TSB NUMBER     | TSB DATE   | TSB TITLE                                            |
|----------------|------------|------------------------------------------------------|
| 93018          | 1993/04/30 | Seat Belt - Retractor Sensor Installation, Rear      |
| 93020          | 1993/04/23 | Campaign - Rear Seat Belts Lock When Parked At Angle |
| 93003          | 1993/04/09 | Campaign - Radio Replacement                         |
| NHTSA93V056002 | 1993/04/09 | Recall 93V056002: Incorrect Seat Belt Lockup Angle   |
| NHTSA93V056001 | 1993/04/09 | Recall 93V056001: Rear Seat Belt Sensor Replacement  |
| NHTSA93V056000 | 1993/04/09 | Recall 93V056000: Seat Belt Sensor Replacement       |
| 91019          | 1993/02/05 | Emissions - Label Replacement Information            |
| 92022          | 1993/01/22 | Mirror - Wind Noise Near Door Mirror Area            |
| 92041          | 1992/11/13 | Engine - Vehicle Fails State I/M Emission Test       |
| 92040          | 1992/11/13 | Tools - Crankshaft Pulley Holder                     |
| 91001          | 1992/11/13 | Window - Noise While Raising or Lowering Window      |
| 92036          | 1992/10/30 | Radio - Poor Reception or Interference On AM Band    |
| 91004          | 1992/10/30 | Seat Belt - Torn Seal On Track                       |
| 92034          | 1992/09/25 | Interior - Glove Box Door Misaligned, Light Stays ON |
| ATRATB132      | 1992/09/01 | A/T - Intermittent Electrical Problems               |
| 92029          | 1992/08/28 | Interior - Glove Box Rattle and Squeaks              |
| ATRATB125      | 1992/08/01 | A/T - Bind-Up In 4th Gear                            |
| SN920703       | 1992/07/01 | Rearview Mirror - Tension Adjustment                 |
| ATRATB116      | 1992/06/01 | A/T - Noise Going Into or Out Of Reverse             |
| SN920504       | 1992/05/01 | M/T - Stuck In Two Gears                             |
| SN920505       | 1992/05/01 | A/C - Odors From Vents                               |
| 92010          | 1992/04/24 | Driveshaft - Joint Boot Leaks Grease                 |
| 90026          | 1992/04/03 | Body - Fuel Filler Door Does Not Open Properly       |
| 92018          | 1992/04/03 | Interior - Cup Holder Won't Stay Closed              |
| 89042          | 1992/04/03 | Cup Holder Buzz                                      |

| TSB NUMBER     | TSB DATE   | TSB TITLE                                                |
|----------------|------------|----------------------------------------------------------|
| 92017          | 1992/03/27 | Window - Motor Runs But the Window Does Not Move         |
| SN920301       | 1992/03/01 | Parasitic Draw - Test Clarifications                     |
| 89027          | 1992/02/28 | Engine - Distributor Repair Procedure                    |
| 92011          | 1992/02/28 | Windows - Door Glass Rattles                             |
| 92006          | 1992/02/28 | Keyless Entry - Inoperative                              |
| MESSAGEA03     | 1992/02/26 | Campaign - Trunk Spring Product Improvement              |
| 92001          | 1992/01/31 | Engine - Charging System Testing                         |
| SN920102       | 1992/01/01 | High Mount Brake Light - Clip Availability               |
| ATRATB090      | 1992/01/01 | A/T - 4 Speed Pressure Specifications                    |
| SN911206       | 1991/12/01 | Nose Mask - May Cloud Paint                              |
| SN911205       | 1991/12/01 | `B' Pillar - Creaking Noise                              |
| 91035          | 1991/11/27 | Engine - Camshaft Oil Seal Leaking                       |
| 91013          | 1991/11/22 | Interior - Sun Visor Damaged By Seat Belt                |
| 91032          | 1991/11/08 | Lighting - High Mount Sealing Gasket Loose or Falls Off  |
| 91033          | 1991/11/08 | Recall - Cargo Area Light Defect                         |
| NHTSA91V195000 | 1991/11/08 | Recall 91V195000: Cargo Lamp Defect                      |
| 90027          | 1991/11/01 | Body - Paint Codes                                       |
| 90031          | 1991/11/01 | Suspension - Noise From Right Rear                       |
| ATRATB078      | 1991/11/01 | A/T - How To Use A Pressure Gauge                        |
| 91028          | 1991/10/25 | Campaign - A/T Shaft Nut May Loosen                      |
| 91003          | 1991/10/04 | Campaign - Trunk Lid Doesn't Stay Open All the Way       |
| ATRATB068      | 1991/09/01 | A/T - Computer Diagnostics                               |
| ATRATB069B     | 1991/09/01 | A/T - 4 Speed Identification                             |
| 90038          | 1991/08/16 | Brakes - Anti-Lock Brake Problem Code 1/Leaking Solenoid |
| 91023          | 1991/07/26 | Body - Kick Panel Water Leak                             |

| TSB NUMBER | TSB DATE   | TSB TITLE                                               |
|------------|------------|---------------------------------------------------------|
| 91024      | 1991/07/26 | Body - Loose or Missing Roof Rack Molding or End Covers |
| 91022      | 1991/07/12 | Windshield - Water Leak On the Front Floor Area         |
| SN910701   | 1991/07/01 | ECU Connector - Terminal Removal                        |
| SN910705   | 1991/07/01 | Accessory Wiring - Damages Fuse Block                   |
| SN910704   | 1991/07/01 | Fog Lights - Stay ON With Key Off                       |
| SN910703   | 1991/07/01 | Crank/Rod Journal - Identification                      |
| 91018      | 1991/06/07 | Warranty Policy - Assembly/Component Replacement        |
| 91015      | 1991/05/31 | Instruments - Odometer/Trip Meter Stops Registering     |
| 90020      | 1991/05/17 | Windows - Windshield/Cowl Water Leaks                   |
| 91014      | 1991/05/17 | Body - Roof Molding Trough Water Leak                   |
| 91012      | 1991/05/03 | Door Locks - Door Locks Cycle                           |
| 90032      | 1991/03/29 | Doors - Front Door Is Difficult to Open                 |
| 91006      | 1991/03/01 | Seats - Headrest Lower Seam Detaches                    |
| SN910203   | 1991/02/01 | Trailer Hitches and Wiring                              |
| SN910202   | 1991/02/01 | Security System - Programming                           |
| SN910201   | 1991/02/01 | CD Player - Skips                                       |
| 86027      | 1990/12/21 | Tools - Engine Stand and Adapter Information            |
| 90037      | 1990/12/21 | Tools - Instructions For New Ball Joint Tool            |
| 90035      | 1990/12/21 | Door - Removal of Door Edge Guard                       |
| ATRATB028  | 1990/10/01 | A/T - Engine Vacuum Testing                             |
| SN900902   | 1990/09/01 | EGR Test Harness - Service Manual Correction            |
| 90022      | 1990/08/10 | Tools - Anti-Lock Brake Checker Repair                  |
| SN900806   | 1990/08/01 | Radio - Noise/Interference Service Tip                  |
| SN900805   | 1990/08/01 | Cigarette Lighter - Switching Precautions               |
| SN900705   | 1990/07/01 | Recycled R12 - Storage Tips                             |

| TSB NUMBER    | TSB DATE   | TSB TITLE                                      |
|---------------|------------|------------------------------------------------|
| SN900603      | 1990/06/01 | R12 Refrigerant - Recovery/Recycling Update    |
| SN900304      | 1990/03/01 | Water Pump - Coolant Weepage                   |
| ATRATB9002006 | 1990/02/01 | A/T - Choosing the Right ATF                   |
| ATRATB8930    | 1989/10/01 | A/T - Math Part II                             |
| ATRATB8927    | 1989/09/01 | A/T - Twenty Steps To Successful Repairs       |
| ATRATB8923    | 1989/08/01 | A/T - Math Formulas Part I                     |
| 89008         | 1989/02/17 | Tools - Check Mainshaft End Play               |
| ATRATB8754    | 1987/09/01 | A/T - Front Bushing Wear                       |
| ATRATB8748    | 1987/08/01 | A/T - Slipping or No-Shift/Metal Sealing Rings |