

ALL TECHNICAL SERVICE BULLETINS

☰ Type term and hit enter to filter list below

TSB NUMBER	TSB DATE	TSB TITLE
09-011-20	2020/07/24	6.7L New Oil Usage Information
RC-CW49-20	2020/07/17	Campaign W49 Drag Link
RC-W49-20	2020/07/17	Equipment Safety Recall W49 NHTSA 20E-043 Drag Link
23-015-20 REV. A	2020/06/19	Disinfectant Solution Recommended for COVID-19
23-016-20	2020/06/03	5th Wheel/Gooseneck Trailer Hitch Does Not Fit
31-001-20	2020/02/11	Blending Clearcoat During The Refinish Process
08-010-20	2020/01/18	RA3 and RA4 GPS Calibration Update
RC-VB3-19	2019/11/21	Customer Satisfaction Notification VB3 Navigation Flash
31-004-19	2019/11/20	Authentic Mopar® Glass Replacement
31-005-19	2019/11/20	Use of Aftermarket Parts
31-006-19	2019/11/20	Repair Parts Used For Structural Repairs
31-003-19	2019/11/20	Use of Salvage/Recycled Parts
31-002-19	2019/09/25	Scan Tool Support Before and After Collision Repair
RC-CV44-19	2019/09/05	Safety Recall V44 (Transport Canada No. 2019-441) Tailgate Latch
RC-V44-19	2019/09/05	Safety Recall V44 / NHTSA 19V-347 Tailgate Latch
08-089-19	2019/08/28	Flash Over The Air (FOTA) Software Update RA3 and RA4 Radio
19-001-19	2019/06/20	Toe Adjustment With Welded Drag Link
RC-V06-19	2019/06/06	Safety Recall V06 / NHTSA 19V-021 Drag Link
RC-CV06-19	2019/06/04	Safety Recall V06 Drag Link
08-030-19	2019/04/03	Flash: Instrument Panel Cluster (IPC) Updates

TSB NUMBER	TSB DATE	TSB TITLE
RC-U40-19	2019/03/21	Equipment Safety Recall U40 NHTSA 18E-028 Mopar Gooseneck Ball Kit
RC-CU40-18	2019/03/20	Campaign U40 Mopar Gooseneck Ball Kit
RC-T79-18	2019/01/14	Safety Recall T79 / NHTSA 17V-821 Brake Transmission Shift Interlock
31-002-18	2018/11/10	Safety Certification and Tire Pressure Label Replacement Guidelines
RC-U53-18	2018/11/06	Customer Satisfaction Notification U53 Occupant Restraint Control Module
RC-CU53-18	2018/11/06	Customer Satisfaction Notification U53 Occupant Restraint Control Module
RC-U74-18	2018/09/26	Safety Recall U74 / NHTSA 18V- 486 Tailgate Latch
26-001-18	2018/09/21	Fluid Flushing Requirements
RC-CT82-18	2018/09/19	Safety Recall T82 Fire Extinguisher
RC-CU74-18	2018/09/12	Safety Recall U74 - Tailgate Latch
RC-T51-17	2018/08/28	Safety Recall T51 / NHTSA 17V-562 Diesel Water Pump
RC-CT79-18	2018/08/13	Safety Recall T79 Brake Transmission Shift Interlock
RC-U30-18	2018/08/07	Customer Satisfaction Notification U30 Transmission Solenoid Pack
24-008-18	2018/07/13	A/C Systems Contain Fluorescent Leak Check Dye in Factory Fill
RC-CU61-18	2018/06/27	Safety Recall U61 Reprogram Powertrain Control Module
RC-U61-18	2018/06/26	Safety Recall U61 / NHTSA 18V-332 Reprogram Powertrain Control Module
08-045-18 REV.A	2018/06/08	Flash: RA3 and RA4 Radio Enhancements
RC-T82-18	2018/05/03	Safety Recall T82 / NHTSA 17V-824 Fire Extinguisher
23-015-18	2018/04/19	Headlamp Condensation and Fogging
08-016-18 REV.A	2018/03/30	RG3 RG4 RJ3 RJ4 Radio Enhancements
18-015-18	2018/02/23	Flash: Powertrain Diagnostic and System Improvements

TSB NUMBER	TSB DATE	TSB TITLE
RC-CT51-17	2018/02/22	Safety Recall T51 Diesel Water Pump
RC-T83-18	2018/02/01	Safety Recall T83 / NHTSA 17E-076 Fire Extinguisher
08-028-17_REV._B	2017/09/08	RA3 and RA4 Radio Over The Air Software Updates
RC-CT25-17	2017/08/03	Safety Recall T25 Occupant Restraint Control Module
RC-T25-17	2017/08/03	Safety Recall T25 / NHTSA 17V-302 Occupant Restraint Control Module
NHTSA17V302000	2017/05/09	Side Curtain Air Bags may not Deploy in a Rollover
04-001-17	2017/03/18	Failure Code Change
25-001-17	2017/03/02	Diesel Exhaust Fluid
RC-CT13-17	2017/03/01	Customer Satisfaction Notification T13 Manual Transmission Shift Lever
RC-T13-17	2017/03/01	Customer Satisfaction Notification T13 Manual Transmission Shift Lever
08-017-17	2017/02/10	Flash - BCM Diagnostic And System Improvements
08-012-17	2017/02/02	RA2 Radio Software Enhancements
RC-S87-17	2017/01/02	Emissions Recall S87 Selective Catalytic Reduction Catalyst
RC-CS87-17	2017/01/02	Emissions Recall S87 Selective Catalytic Reduction Catalyst
23-057-16	2016/12/23	Cold Weather Grille Covers
08-046-16_REV._A	2016/11/11	Flash - Air Suspension Control Module (ASCM) System Enhancements
02-006-16	2016/10/29	Toe Adjustment - Recirculating Ball Steering System
08-082-16	2016/10/18	Flash - Integrated Trailer Brake Module Software Enhancement
08-044-16_REV._B	2016/10/15	Flash - Radio Frequency Hub Module (RFHM) Enhancement
S58	2016/09/01	NHTSA 16V-559 Front Suspension Track Bar Frame Bracket
NHTSA16V559000	2016/07/26	Recall - Weld Failure May Reduce Steering Ability
S30	2016/07/01	Safety Recall S30 NHTSA 16E-041 Mopar Canvas Seat Covers

TSB NUMBER	TSB DATE	TSB TITLE
RC-CS30-16	2016/06/01	Safety Recall S30 Mopar Canvas Seat Covers
23-001-16E	2016/05/26	Center Console Lid Binding
09-004-16A	2016/04/09	Engine - Cummings Service Engine Replacement
S03	2016/04/01	Safety Recall S03 / NHTSA 16V-043 - Wheel Chocks
17-002-15	2015/12/12	Suspension - MIL ON, DTC C1556-14
05-013-15	2015/12/10	ABS TCS - ESC Warning Lamp On, DTC C996A-49
03-004-15	2015/12/05	Drivetrain - Vibration Towing Heavy Loads, 0-11 MPH
08-111-15	2015/11/13	Audio - RA1 Radio Enhancements
23-044-15	2015/11/11	Body - Gap between Wheel Opening Moulding and Body
08-110-15	2015/11/11	Lighting - LED Turn Signal Lamps Do Not Display Correctly
08-108-15	2015/11/05	Drivetrain - Power Take Off Enhancements
23-037-15	2015/10/14	Windshield Wiper Blade/Element Maintenance
R40	2015/09/01	Safety Recall R40 / NHTSA 15V-461 - Radio Security Vulnerability
31-001-15	2015/08/27	Interior - Replacement Seat Covers and Seat Cover Repairs
08-081-15	2015/08/22	Infotainment - UConnect(R) Can Not Be Registered
23-033-15	2015/08/22	Body - Rattle/Clunking/Popping Noise On Uneven Roads
R23	2015/08/15	Recall - Reprogram Occupant Restraint Control Module
25-001-15A	2015/08/12	Emissions - Diesel Exhaust Fluid Level Sensor is Defective
RC-CR23-15	2015/08/01	Safety Recall R23 Reprogram Occupant Restraint Control Module
08-029-15A	2015/07/09	Audio System - RG2 or RJ2 radio Software Enhancements
08-047-15B	2015/06/05	Lighting - Headlamp Low Beams Appear Dim or Yellow
08-043-15	2015/04/29	Mirrors - Power Fold/Unfold Switch Inoperative
22-002-15A	2015/03/28	Tire Monitor System - Service TPMS Message, DTC's Set
08-030-15	2015/03/27	Lighting - Auto Headlamps Don't Turn Off After Exiting Darkness
02-003-15	2015/01/27	Steering/Suspension - Vehicle Pulls To The Left or Right

TSB NUMBER	TSB DATE	TSB TITLE
02-002-15	2015/01/27	Steering/Suspension - Steering Wheel Not Centered
02-001-15	2015/01/10	Suspension - Strut/Shock Replacement Guidelines
08-096-14	2014/11/12	Cell Phone - Uconnect Access Buttons are Inoperative
22-001-14A	2014/10/29	Wheels/Tires - Steering Wheel Vibration Diagnostic Procedure
08-091-14	2014/10/24	Lighting - Exterior Lamp Condensation and Fogging
25-003-14	2014/09/06	Engine Controls - MIL ON, DTC's P207F and P1C70 Set