

ALL TECHNICAL SERVICE BULLETINS

☰ Type term and hit enter to filter list below

TSB NUMBER	TSB DATE	TSB TITLE
RC-Z87-22	2022/10/13	Safety Recall Z87 / NHTSA 22V-642 Powertrain Control Module
08-188-22	2022/10/12	Telematics Box Module (TBM) Firmware Over The Air Software 5.25.0 Version Updates
RC-CZ87-22	2022/10/12	SAFETY RECALL Z87 – ENGINE CONTROL MODULE
21-030-22	2022/10/05	Flash: Transmission Control Module (TCM) Updates
08-160-22 REV. B	2022/09/23	Radio Over The Air R141.01.12, 139.01.53, 136.10.04 to R145.00.15 Software Version Updates
18-094-22 REV. A	2022/09/10	Flash: Powertrain Control Module (PCM) Update
31-001-22	2022/08/19	Approved Use of Weld Through Primers
08-123-22 REV. B	2022/07/27	Flash: Display Screen Module (DSM) Updates
RC-Z07-22	2022/06/28	Safety Recall Z07 / NHTSA 21V-925 Side Air Bag Inflatable Curtain Inflator
RC-Y99-22	2022/06/28	Safety Recall Y99 / NHTSA 21V-925 Side Air Bag Inflatable Curtain Inflator
RC-CY99-22	2022/06/28	Safety Recall Y99 Transport Canada 2021-722 Side Air Bag Inflatable Curtain Inflator
RC-CZ07-22	2022/06/28	Safety Recall Z07 Transport Canada 2021-722 Side Air Bag Inflatable Curtain Inflator
08-062-22 REV. C	2022/06/24	UPD UFD UBD UED UBC UEC Radio Enhancements
08-130-22	2022/06/22	Amplifier (AMP) Drone Noise
RC-Y56-22	2022/06/15	Equipment Safety Recall Y56 / NHTSA 21V-632 Side Air Bag Inflatable Curtain Inflator
RC-CY56-22	2022/06/15	Equipment Campaign Y56 Side Air Bag Inflatable Curtain Inflator
08-120-22	2022/06/10	Radio Over the Air Software Version Updates

TSB NUMBER	TSB DATE	TSB TITLE
08-031-22 REV. A	2022/03/29	Radio Over The Air Software Version Updates
08-025-22 REV. A	2022/02/26	Radio Over The Air Software Version Updates
08-036-22	2022/02/24	Radio Enhancements
08-009-22	2022/01/12	Radio Over The Air Software Version Updates
RC-CY76-21	2022/01/11	Safety Recall Y76 Transport Canada 2021-629 Intake Air Heater Relay
RC-Y76-21	2022/01/11	Safety Recall Y76 / NHTSA 21V-798 Intake Air Heater Relay
18-095-21	2021/12/17	wiTECH Small Leak Verification Test (SLVT) - P0456-EVAP SYSTEM SMALL LEAK
08-185-21	2021/12/14	Flash: Security Gateway Module (SGW) Enhancements
08-180-21 REV. A	2021/12/09	Radio Over The Air Software Version Updates
18-034-21 REV. A	2021/11/10	P203E and P203F Additional Diagnostic Information
08-155-21 REV. A	2021/10/28	Radio Enhancements
08-155-21	2021/10/02	Radio Enhancements