

ALL TECHNICAL SERVICE BULLETINS

☰ Type term and hit enter to filter list below

TSB NUMBER	TSB DATE	TSB TITLE
08-158-23	2023/06/30	Radio Over The Air Update to T25.48 Software Version
24-006-23	2023/06/30	A/C Diagnostic LOP Change
RC-C70A-23	2023/06/29	Customer Satisfaction Notification Radio Date and Time Update
RC-70A-23	2023/06/29	Customer Satisfaction Notification Radio Date/Time Update
03-003-23	2023/06/24	Clicking Noise While In 4wd
19-005-23	2023/05/27	Steering Column Intermediate Shaft Noise
08-130-23	2023/05/26	Telematics Box Module (TBM) Over The Air Software Update to 5.39.1
RC-C13A-23	2023/05/24	Safety Recall 13A Transport Canada 2023-026 Intake Air Grid Heater Relay
RC-13A-23	2023/05/23	Safety Recall 13A / NHTSA 23V-060 Intake Air Grid Heater Relay
07-007-23	2023/05/18	Water Quality When Mixed With Engine Coolant
08-105-23 REV. A	2023/05/06	Radio S26.17 USB Software Update
RC-Y76-23	2023/04/21	Safety Recall Y76 / NHTSA 21V-798 Intake Air Heater Relay
14-003-23	2023/04/15	Diesel Exhaust Fluid (DEF) Fluid Freezing
08-082-23	2023/04/07	UPD UFD UBD UED UBC UEC Radio Enhancements
08-079-23	2023/04/04	Radio Over The Air Uconnect R1L Radio Software Update to R160
RC-C17A-23	2023/03/28	Equipment Campaign 17A Rearview Camera
RC-17A-23	2023/03/28	Equipment Safety Recall 17A / NHTSA 23E-009 Rearview Camera
RC-CZD4-23	2023/03/25	Customer Satisfaction Notification ZD4 Diesel Exhaust Fluid
RC-ZD4-23	2023/03/24	Customer Satisfaction Notification ZD4 Diesel Exhaust Fluid
RC-C18A-23	2023/03/23	Equipment Campaign 18A Intake Air Grid Heater Relay

TSB NUMBER	TSB DATE	TSB TITLE
RC-18A-23	2023/03/23	Equipment Safety Recall 18A NHTSA 23E-010 Intake Air Grid Heater Relay
RC-ZA3-22	2023/03/21	Safety Recall ZA3 / NHTSA 22V-835 Transmission Dipstick
RC-CZA3-22	2023/03/21	Safety Recall ZA3 Transmission Dipstick
31-001-23 REV. A	2023/03/04	Aluminum Body Panel Corrosion Repair
08-044-23	2023/02/14	Radio Over The Air S24.13 and S24.18 Updating to S26.17 Software Version
08-040-23	2023/02/01	Radio Over The Air R141.01.12, 139.01.53, 136.10.04 to R145.00.15 Software Version Updates
08-026-23	2023/01/26	RCA Amplifier Drone Noise
08-028-23	2023/01/26	Radio Over The Air Updating to S26.17 Software Version
18-005-23	2023/01/12	Flash: Powertrain Control Module (PCM) Updates
08-006-23	2023/01/06	6.7L Cummins No Start
RC-ZB8-22	2022/12/15	Safety Recall ZB8 / NHTSA 22V-904 Tailgate Latch Alignment
RC-CZB8-22	2022/12/15	Safety Recall ZB8 Transport Canada 2022-699 Tailgate Latch Alignment
23-051-22	2022/11/30	RamBox Applique Separation/Delamination
08-194-22	2022/10/25	Radio VIN Lock
RC-Z87-22	2022/10/13	Safety Recall Z87 / NHTSA 22V-642 Powertrain Control Module
08-188-22	2022/10/12	Telematics Box Module (TBM) Firmware Over The Air Software 5.25.0 Version Updates
RC-CZ87-22	2022/10/12	SAFETY RECALL Z87 – ENGINE CONTROL MODULE
RC-CZ47-22	2022/08/24	Safety Recall Z47 Transport Canada 2022-304 Rearview Camera Visibility
RC-Z47-22	2022/08/24	Safety Recall Z47 / NHTSA 22V-407 Rearview Camera Visibility
31-001-22	2022/08/19	Approved Use of Weld Through Primers
08-123-22 REV. B	2022/07/27	Flash: Display Screen Module (DSM) Updates

TSB NUMBER	TSB DATE	TSB TITLE
RC-Z07-22	2022/06/28	Safety Recall Z07 / NHTSA 21V-925 Side Air Bag Inflatable Curtain Inflator
RC-CY99-22	2022/06/28	Safety Recall Y99 Transport Canada 2021-722 Side Air Bag Inflatable Curtain Inflator
RC-Y99-22	2022/06/28	Safety Recall Y99 / NHTSA 21V-925 Side Air Bag Inflatable Curtain Inflator
RC-CZ07-22	2022/06/28	Safety Recall Z07 Transport Canada 2021-722 Side Air Bag Inflatable Curtain Inflator
RC-Y56-22	2022/06/15	Equipment Safety Recall Y56 / NHTSA 21V-632 Side Air Bag Inflatable Curtain Inflator
RC-CY56-22	2022/06/15	Equipment Campaign Y56 Side Air Bag Inflatable Curtain Inflator
08-120-22	2022/06/10	Radio Over the Air Software Version Updates
RC-CZ20-22	2022/05/19	Safety Recall Z20 Transport Canada 2022-108 Electronic Stability Control
RC-CZ25-22	2022/04/30	Equipment Campaign Z25 Electronic Stability Control
RC-Z25-22	2022/04/29	Equipment Safety Recall Z25 / NHTSA 22V-E017 Electronic Stability Control
08-031-22 REV. A	2022/03/29	Radio Over The Air Software Version Updates
08-025-22 REV. A	2022/02/26	Radio Over The Air Software Version Updates
08-036-22	2022/02/24	Radio Enhancements
08-009-22	2022/01/12	Radio Over The Air Software Version Updates
RC-CY76-21	2022/01/11	Safety Recall Y76 Transport Canada 2021-629 Intake Air Heater Relay
08-185-21	2021/12/14	Flash: Security Gateway Module (SGW) Enhancements
08-180-21 REV. A	2021/12/09	Radio Over The Air Software Version Updates
18-034-21 REV. A	2021/11/10	P203E and P203F Additional Diagnostic Information