



CONNECTOR REPAIR KITS

- [Home](#)
- [FAQ](#)
- [Repair Parts](#)
- [Splicing Procedure](#)
- [Feedback](#)


Diagram

[Back to Results](#) [Print](#)

WIRING-TRAILER TOW 7-WAY - BLACK 10 WAY


Full Repair Kit: 05017114AA

End View



WIRING- TRAILER TOW 7-WAY

Isometric View



Pin Information

Cav	Circuit	Gauge	Color	Function
1			-	
2	L674	18	LG	TRAILER TOW RIGHT TURN RELAY OUTPUT
3	L1	18	WT/LG	BACKUP LAMP FEED
4	A100	14	RD/VT	FUSED B(+)
5	L678	18	BR	FUSED PARK LAMP FEED
6			-	
7	B40	14	DG	TRAILER TOW BRAKE B(+)
8	Z927	14	BK	GROUND
9	Z927	14	BK	GROUND
10	L673	18	YL	TRAILER TOW LEFT TURN RELAY OUTPUT

Removal Tools

A specific removal tool has not been identified.

Terminal Repair Kits

No terminal repair kits have been identified.



Mopar is a registered trademark of Chrysler Group LLC. © Copyright 2011 Chrysler Group LLC. All Rights Reserved. Chrysler, Jeep, Dodge, Ram, Mopar and the Pentastar logo are registered trademarks of Chrysler Group LLC. FIAT is a registered trademark of Fiat Group Marketing & Corporate Communication SpA, used under license by Chrysler Group, LLC. GEM and design is a registered trademark of Chrysler Group Global Electric Motorcars LLC, a wholly owned subsidiary of Chrysler Group LLC. ©2011 Chrysler Group LLC, All Rights Reserved. v1.3.6 Built:03/27/2017